

Nach dem Öffnen des Files in Excel müssen die Makros aktiviert werden. Sollte das nicht gehen, müssen Sie zuvor Ihre Sicherheits-Einstellung verändern. Dazu gehen Sie auf Extras/Makro/Sicherheit und ändern die Einstellung auf "mittel". Danach File speichern, schließen und nochmals öffnen. Nun die Makros aktivieren.

```
' these variables are shared by all routines in this module
Dim ANT(3, 5) As Double
Dim VI(5) As Double
Dim PARAM(5, 5) As Double
Dim NK As Integer
Dim NK1 As Integer
Dim NST As Integer
Dim ITEXT As String
Dim ws As Object, wsfp As Object, wsfpd As Object, wsmfd As Object
```

```
Public Sub desw_execute()
' This program is based on UNIDIST developed in the group
' of Prof. Aa. Fredenslund at the Technical University of Lyngby in Denmark
' It was modified for Excel-VBA by Dr. J. Rarey, University of Oldenburg, Germany

' IMPLICIT REAL*8 (A-H,O-Z)
Dim P(50) As Double
Dim XX(5) As Double
Dim Index(50) As Integer
Dim PROD(6) As Double
Dim FEED(6) As Double
Dim FL(50) As Double
Dim FV(50) As Double
Dim FLL(50, 5) As Double
Dim T(50) As Double
Dim BMAT(50, 7, 6) As Double
Dim D(50, 6) As Double
Dim CM(6, 13) As Double
Dim Pi(5) As Double
Dim DPI(5, 6) As Double
Dim SL(50) As Double
Dim SV(50) As Double
Dim FKV(50) As Double
Dim FSTR(50, 6) As Double

' get current input sheet and set variables for output sheets
Set ws = ActiveSheet
Set wsfp = Sheets("Flux Profile")
On Error GoTo 21
Set wsfpd = Sheets("Flux Profile Diagram")
Set wsmfd = Sheets("Mole Fraction Profile Diagram")
```

```

21: On Error GoTo 0
If Not wsfpd Is Nothing Then wsfpd.Delete
If Not wsmfd Is Nothing Then wsmfd.Delete

' Clear Output-Sheets
wsfp.Cells.ClearContents

' number of components
NK = ws.Cells(5, 2)

' title text
ITEXT = ws.Cells(6, 2)

' Wilson parameters PARAM(I,J) (U(J,I) - U(I,I))
For i = 1 To NK
    For N = 1 To NK
        PARAM(i, N) = ws.Cells(17 + i, 1 + N)
    Next N
Next i

' molar volumes (CM3/MOL) and Antoine-constants (kPa)
For i = 1 To NK
    VI(i) = ws.Cells(9 + i, 2)
    For k = 1 To 3
        ANT(k, i) = ws.Cells(9 + i, 2 + k)
    Next k
Next i

For i = 1 To NK
    ANT(1, i) = 2.3025851 * ANT(1, i)
    ANT(2, i) = 2.3025851 * ANT(2, i)
Next i

NST = ws.Cells(25, 2)
NFEED = ws.Cells(26, 2)
NSL = ws.Cells(27, 2)
NSV = ws.Cells(28, 2)

Index(1) = 1
NSL1 = NSL + 1
NSL2 = NSL + 2
Index(NSL2 + NSV) = -NST
IK = 1

' EINGABE: DESTILLATMENGE, RUECKLAUFVERHAELTNIS, DRUCK IM KOPF
UND
' SUMPF DER KOLONNE (KPA), SCHAETZWERTE FUER DIE TEMPERATUR AM
KOPF

```

```

' UND IM SUMPF DER KOLONNE (C)
DEST = ws.Cells(29, 2)
RFLX = ws.Cells(30, 2)
PT = ws.Cells(31, 2)
PB = ws.Cells(32, 2)
TT = ws.Cells(33, 2)
TB = ws.Cells(34, 2)

' FLMAX: MAXIMALE AENDERUNG DER STROEME (Z.B. 0.5), DTMAX: MAXI-
' MALE TEMPERATURAENDERUNG WAEHREND DER ITERATION (Z.B. 10.)
DTMAX = ws.Cells(35, 2)
FLMAX = ws.Cells(36, 2)

NK1 = NK + 1
For i = 1 To NST
    P(i) = PB - (PB - PT) / CDbl(NST - 1) * CDbl(i - 1)
    SL(i) = 0#
    SV(i) = 0#
    FKV(i) = 0#
    FSTR(i, NK1) = 0#
    For j = 1 To NK
        FSTR(i, j) = 0#
    Next j
    Next i
    For i = 1 To NFEED
        EINGABE DES ZULAUFBODENS, -BEDINGUNGEN UND -MENGEN
        NF = ZULAUFBODEN
        NF = ws.Cells(39 + i, 2)
        FKV = DAMPFANTEIL DES ZULAUFS
        FSTR(NF,I) MENGE DER KOMPONENTE I IM ZULAUF
        FKV(NF) = ws.Cells(39 + i, 3)
        For j = 1 To NK
            FSTR(NF, j) = ws.Cells(39 + i, 3 + j)
        Next j
        For j = 1 To NK
            FSTR(NF, NK1) = FSTR(NF, NK1) + FSTR(NF, j)
        Next j
        Next i
        If NSL <> 0 Then
            For i = 1 To NSL
                NLS = BODEN FUER DEN FLUESSIGEN SEITENSTROM
                NLS = ws.Cells(51 + i, 2)
                IK = IK + 1
                Index(IK) = NLS
                SL = MENGE DES FLUESSIGEM SEITENSTROMS
                SL(NLS) = ws.Cells(51 + i, 3)
            Next i
        End If
        If NSV <> 0 Then
            For i = 1 To NSV
                IK = IK + 1

```

```

' NVS = BODEN FUER DEN DAMPFFOERMIGEN SEITENSTROM
NVS = ws.Cells(63 + i, 2)
Index(IK) = -NVS
' SV = MENGE DES DAMPFFOERMIGEN SEITENSTROMS
SV(NVS) = ws.Cells(63 + i, 3)
Next i
End If
' BERECHNUNG DER FLUESSIGKEITS- UND DAMPFSTROEME AUF DEN BOEDEN
' (CONSTANT MOLAL OVERFLOW)
FV(NST) = DEST + FKV(NST) * FSTR(NST, NK1)
FL(NST) = DEST * RFLX + (1# - FKV(NST)) * FSTR(NST, NK1) - SL(NST)
FV(NST - 1) = FL(NST) - FSTR(NST, NK1) + SV(NST) + SL(NST) + DEST
For ii = 3 To NST
If NST > 2 Then
    i = NST + 2 - ii
    FL(i) = FL(i + 1) - SL(i) + (1# - FKV(i)) * FSTR(i, NK1)
    FV(i - 1) = FV(i) + SV(i) - FKV(i) * FSTR(i, NK1)
End If
Next ii
FL(1) = FL(2) - SL(1) + (1# - FKV(1)) * FSTR(1, NK1)
FL(1) = FL(1) - FV(1)
For j = 1 To NK1
    FEED(j) = 0#
    For i = 1 To NST
        FEED(j) = FEED(j) + FSTR(i, j)
    Next i
    Next j

' ERSTE ABSCHAETZUNG DES TEMPERATUR- UND KONZENTRATIONS profils
For i = 1 To NST
    T(i) = TB + (i - 1) * (TT - TB) / NST
Next i

' IRES = EXPONENT FUER DAS ABBRUCHKRITERIUM RLIM= 10.D00**(-IRES)
IRES = ws.Cells(37, 2)
rlim = 10# ^ (-IRES)

For i = 1 To NST
    For j = 1 To NK
        FLL(i, j) = FEED(j) / FEED(NK1) * FL(i)
    Next j
    Next i

NIT = 0
res = 10# * rlim
While res > rlim
    NKA = NK - 1
    NIT = NIT + 1

' BERECHNUNG DER AKTIVITAETS KOEFFIZIENTEN UND DER ABLEITUNG

```

' NACH DER TEMPERATUR UND DER MOLMENGEN

For i = 1 To NST

For j = 1 To NK

XX(j) = FLL(i, j)

Next j

FLSUM = FL(i)

Call WILSON(T(i), XX, Pi, DPI, FLSUM)

For j = 1 To NK

For k = 1 To NKA

BMAT(i, j, k) = (DPI(j, k) - DPI(j, NK)) / P(i)

Next k

BMAT(i, j, NK) = DPI(j, NK + 1) / P(i)

BMAT(i, NK + 1, j) = Pi(j) / P(i)

Next j

Next i

'200 CONTINUE

For IK = 1 To NST

i = NST + 1 - IK

ip = 2 * NK + 1

If i = 1 Then ip = NK + 1

D(i, NK) = -1 + BMAT(i, NK + 1, NK)

For j = 1 To NKA

D(i, NK) = D(i, NK) + BMAT(i, NK + 1, j)

D(i, j) = FSTR(i, j) - FLL(i, j) * (1 + SL(i) / FL(i))

D(i, j) = D(i, j) - BMAT(i, NK1, j) * (FV(i) + SV(i))

If i <> 1 Then D(i, j) = D(i, j) + BMAT(i - 1, NK1, j) * FV(i - 1)

If i <> NST Then D(i, j) = D(i, j) + FLL(i + 1, j)

' AUFSTELLEN DER JACOBI-MATRIX UND LOESUNG DER TRIDIAGONALEN

MATRIX DURCH GAUSSSCHE ELIMINIERUNG

For k = 1 To NK

If i <> 1 Then CM(j, k + NK) = BMAT(i - 1, j, k) * FV(i - 1)

CM(j, k) = -BMAT(i, j, k) * (FV(i) + SV(i))

Next k

Next j

For j = 1 To NKA

CM(j, j) = CM(j, j) - 1 - SL(i) / FL(i)

Next j

For j = 1 To NK

CM(NK, j) = 0#

CM(NK, j + NK) = 0#

CM(j, ip) = D(i, j)

For k = 1 To NK

CM(NK, j) = CM(NK, j) + BMAT(i, k, j)

Next k

Next j

If i <> NST Then

```

For j = 1 To NKA
  CM(j, ip) = CM(j, ip) - D(i + 1, j)
  For k = 1 To NK
    CM(j, k) = CM(j, k) - BMAT(i + 1, j, k)
  Next k
  Next j
End If
Call GAUSL(6, 13, NK, ip - NK, CM)

```

```

For j = 1 To NK
  D(i, j) = CM(j, ip)
  If i <> 1 Then
    For k = 1 To NK
      BMAT(i, j, k) = CM(j, k + NK)
    Next k
  End If
  Next j

```

```
'300 CONTINUE
Next IK
```

```

For i = 2 To NST
  For j = 1 To NK
    For k = 1 To NK
      D(i, j) = D(i, j) - BMAT(i, j, k) * D(i - 1, k)
    Next k
    Next j
  Next i

```

res = 0#

' AENDERUNG DER UNABHAENGIGEN VARIABLEN NACH DER NEWTON-RAPHSON METHODE

```

For i = 1 To NST
  Q = Abs(D(i, NK) / DTMAX)
  If Q > 1# Then D(i, NK) = D(i, NK) / Q
  T(i) = T(i) - D(i, NK)
  D(i, NK) = 0#
  FLM = FLMAX * FL(i)
  For j = 1 To NKA
    D(i, NK) = D(i, NK) - D(i, j)
  Next j

```

Sum = 0#

For j = 1 To NK

Q = Abs(D(i, j) / FLM)

' BERECHNUNG DER FEHLERQUADRATSUMME

res = res + Q * Q

If Q > 1# Then D(i, j) = D(i, j) / Q

FLL(i, j) = FLL(i, j) - D(i, j)

If FLL(i, j) < 0# Then FLL(i, j) = 0#

Sum = Sum + FLL(i, j)

Next j

```

Q = FL(i) / Sum
For j = 1 To NK
    FLL(i, j) = FLL(i, j) * Q
Next j
Next i
'   WRITE (NAG,502) RES,T(1),T(NST)
' 502 FORMAT(/, WERT DER ZIELFUNKTION='E12.3,' TB ='E12.3,' TT ='E12.3)
'C   UEBERPRUEFUNG DES ABBRUCHKRITERIUMS
Wend

' write flux report column header
wsfp.Cells(1, 1) = "Calculation Output"
wsfp.Cells(3, 1) = "Stage"
wsfp.Cells(3, 2) = "Temperature"
wsfp.Cells(4, 2) = "°C"
wsfp.Cells(3, 3) = "Pressure"
wsfp.Cells(4, 3) = "kPa"
wsfp.Cells(3, 4) = "Total Liquid Flux"
wsfp.Cells(4, 4) = "same as in-unit"
wsfp.Cells(3, 5) = "Component Liquid Flux"
For i = 1 To NK
    wsfp.Cells(4, 4 + i) = "comp. " & i
Next i
wsfp.Cells(3, 5 + NK) = "Component Liquid Mole Fraction"
For i = 1 To NK
    wsfp.Cells(4, 4 + NK + i) = "x" & i
Next i

' write flux report
For i = 1 To NST
    wsfp.Cells(4 + i, 1) = i
    wsfp.Cells(4 + i, 2) = T(i)
    wsfp.Cells(4 + i, 3) = P(i)
    wsfp.Cells(4 + i, 4) = FL(i)
    Suml = 0
    For j = 1 To NK
        wsfp.Cells(4 + i, 4 + j) = FLL(i, j)
        Suml = Suml + FLL(i, j)
    Next j
    For j = 1 To NK
        wsfp.Cells(4 + i, 4 + NK + j) = FLL(i, j) / Suml
    Next j
Next i

```

```

Worksheets("Product Streams").Cells.ClearContents
Worksheets("Product Streams").Cells(1, 1) = "Product Streams"
Worksheets("Product Streams").Cells(3, 1) = "Liquid Product Streams"
Worksheets("Product Streams").Cells(4, 1) = "stage"
Worksheets("Product Streams").Cells(4, 2) = "component streams"

```

```

For j = 1 To NSL1
    i = Index(j)
    Q = 1#
    If i <> 1 Then Q = SL(i) / FL(i)
    For k = 1 To NK
        PROD(k) = Q * FLL(i, k)
    Next k
    Worksheets("Product Streams").Cells(4 + j, 1) = i
    For k = 1 To NK
        Worksheets("Product Streams").Cells(4 + j, 1 + k) = PROD(k)
    Next k
Next j

Worksheets("Product Streams").Cells(4 + NSL1 + 2, 1) = "Vapor Product Streams"
Worksheets("Product Streams").Cells(4 + NSL1 + 3, 1) = "stage"
Worksheets("Product Streams").Cells(4 + NSL1 + 3, 2) = "component streams"

NSLT = NSL2 + NSV
lline = 4 + NSL1 + 3
For j = NSL2 To NSLT
    lline = lline + 1
    i = -Index(j)
    Q = 1#
    If i <> NST Then Q = SV(i) / FV(i)
    Worksheets("Product Streams").Cells(lline, 1) = i
    For k = 1 To NK
        PROD(k) = Q * BMAT(i, NK1, k) * FV(i)
        Worksheets("Product Streams").Cells(lline, 1 + k) = PROD(k)
    Next k
Next j
Call format_results
Charts("Flux Profile Diagram").Activate
End Sub

Sub WILSON(TEMP, FL, Pi, DPI, FLSUM)
    ' DAS UNTERPROGRAMM WILSON ERLAUBT DIE BERECHNUNG DER
    PARTIAL-
    ' DRUECKE UND DER ABLEITUNGEN NACH DER TEMPERATUR UND DER
    MOLMEN
    ' GEN ( BASIS: WILSON- UND ANTOINE-GLEICHUNG)
    ' DIE UEBERGABEPARAMETER HABEN DIE FOLGENDE BEDEUTUNG:
    ' TEMP TEMPERATUR C
    ' FL(I) MOLMENGEN DER KOMPONENTE I I=1,2..NK
    ' GAM(I) AKTIVITAETSKoeffizient BERECHNET MIT DER WILSON-
    GLEICHUNG
    ' PI(I) PARTIALDRUCK DER KOMPONENTE I
    ' DPI(I,J) ABLEITUNG VON PI(I) GENERATED IN WILSON
    ' FUER J=1,2..NK SIND ES DIE ABLEITUNGEN NACH DEN MOLMENGEN
    ' FUER J=NK+1 SIND ES DIE ABLEITUNGEN NACH DER TEMPERATUR

```

```

' IMPLICIT REAL*8 (A-H,O-Z)
Dim GAM(5), PRS(5), DPRS(5), WLAM(5, 5)
!!!!! COMMON/DIST/ANT(3,5),VI(5),PARAM(5,5),NK,NK1
For i = 1 To NK
    PRS(i) = Exp(ANT(1, i) - ANT(2, i) / (ANT(3, i) + TEMP))
    DPRS(i) = ANT(2, i) / (ANT(3, i) + TEMP) ^ 2
Next i
TEMK = TEMP + 273.15

For i = 1 To NK
    For j = 1 To NK
        WLAM(i, j) = VI(j) / VI(i) * Exp(-PARAM(i, j) / TEMK)
    Next j
Next i

For i = 1 To NK
    A1 = 0#
    A2 = 0#
    A3 = 0#
    A4 = 0#
    For k = 1 To NK
        A5 = 0#
        A6 = 0#
        A1 = A1 + FL(k) * WLAM(i, k)
        A2 = A2 + FL(k) * WLAM(i, k) * PARAM(i, k) / TEMK ^ 2
        For j = 1 To NK
            A5 = A5 + FL(j) * WLAM(k, j)
            A6 = A6 + FL(j) * WLAM(k, j) * PARAM(k, j) / TEMK ^ 2
        Next j
        A3 = A3 + FL(k) * WLAM(k, i) / A5
        A4 = A4 + FL(k) * WLAM(k, i) * PARAM(k, i) / TEMK ^ 2 / A5
        A4 = A4 - FL(k) * WLAM(k, i) * A6 / A5 ^ 2
    Next k
    GAM(i) = Exp(-Log(A1 / FLSUM) + 1# - A3)
    Pi(i) = FL(i) / FLSUM * GAM(i) * PRS(i)
    DPI(i, NK1) = Pi(i) * (-A2 / A1 - A4 + DPRS(i))
    For L = 1 To NK
        A7 = 0#
        A9 = 0#
        For k = 1 To NK
            A8 = 0#
            A9 = A9 + FL(k) * WLAM(L, k)
            For j = 1 To NK
                A8 = A8 + FL(j) * WLAM(k, j)
            Next j
            A7 = A7 + FL(k) * WLAM(k, i) * WLAM(k, L) / A8 ^ 2
        Next k
        DPI(i, L) = -WLAM(i, L) / A1 - WLAM(L, i) / A9 + A7
    Next L
Next i

```

```

For i = 1 To NK
  For L = 1 To NK
    S = DPI(i, L) * FL(i)
    If L = i Then S = S + 1
    DPI(i, L) = PRS(i) * GAM(i) / FLSUM * S
  Next L
  Next i
End Sub

Sub GAUSL(ND, NCOL, N, NS, A)
  ' DAS UNTERPROGRAMM GAUSL LOEST N LINEARE ALGEBRAISCHE
  GLEICHUNGEN
  ' DURCH GAUSSSCHE ELIMINIERUNG
  ' IMPLICIT REAL*8 (A-H,O-Z)
'ReDim A(ND, NCOL)
N1 = N + 1
NT = N + NS
If N <> 1 Then
  For i = 2 To N
    ip = i - 1
    i1 = ip
    X = Abs(A(i1, i1))
    For j = i To N
      If Abs(A(j, i1)) >= X Then
        X = Abs(A(j, i1))
        ip = j
      End If
    Next j
    If ip <> i1 Then
      For j = i1 To NT
        X = A(i1, j)
        A(i1, j) = A(ip, j)
        A(ip, j) = X
      Next j
    End If
    For j = i To N
      X = A(j, i1) / A(i1, i1)
      For k = i To NT
        A(j, k) = A(j, k) - X * A(i1, k)
      Next k
    Next j
  Next i
End If
For ip = 1 To N
  i = N1 - ip
  For k = N1 To NT
    A(i, k) = A(i, k) / A(i, i)
  If i <> 1 Then
    i1 = i - 1
    For j = 1 To i1
      A(j, k) = A(j, k) - A(i, k) * A(j, i)
    Next j
  End If
End Sub

```

```
    End If
    Next k
    Next ip
End Sub
```

```
Private Sub format_results()
```

```
' format flux profile report sheet
Sheets("Flux Profile").Select
Range("A1").Select
With Selection.Font
    .Name = "Arial"
    .Size = 16
    .Strikethrough = False
    .Superscript = False
    .Subscript = False
    .OutlineFont = False
    .Shadow = False
    .Underline = xlUnderlineStyleNone
    .ColorIndex = xlAutomatic
End With
Selection.Font.Bold = True
```

```
Range("A3:O3").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
```

```
Columns("B:B").Select
Selection.NumberFormat = "0.000"
Columns("C:C").Select
Selection.NumberFormat = "0.000"
Columns("D:D").Select
Selection.NumberFormat = "0.00"
Columns("E:O").Select
Selection.NumberFormat = "0.00000"
Range("A3:I100").Select
```

```
' add chart
Charts.Add
Dim ser As Object
ActiveChart.ChartType = xlXYScatterLines
On Error Resume Next
For Each ser In ActiveChart.SeriesCollection
    ser.Delete
Next ser
On Error GoTo 0
```

```
' select chart data
undels = ActiveChart.SeriesCollection.Count
```

```

With ActiveChart
    ' Total Flux Curve
    .SeriesCollection.NewSeries
    .SeriesCollection(undels + 1).XValues = "=" & wsfp.Name & "!R" & CInt(5) & "C1:
R" & CInt(4 + NST) & "C1 "
    .SeriesCollection(undels + 1).Values = "=" & wsfp.Name & "!R" & CInt(5) & "C4: R"
& CInt(4 + NST) & "C4 "
    .SeriesCollection(undels + 1).Name = "=" & wsfp.Name & "!R3C4"

    ' Component Flux Curves
    For i = 1 To NK
        .SeriesCollection.NewSeries
        .SeriesCollection(undels + 1 + i).XValues = "=" & wsfp.Name & "!R" & CInt(5) &
"C1: R" & CInt(4 + NST) & "C1 "
        .SeriesCollection(undels + 1 + i).Values = "=" & wsfp.Name & "!R" & CInt(5) &
"C" & CInt(4 + i) & ": R" & CInt(4 + NST) & "C" & CInt(4 + i)
        .SeriesCollection(undels + 1 + i).Name = "=" & wsfp.Name & "!R4C" & CInt(4 + i)
    Next i
End With
ActiveChart.Location Where:=xlLocationAsNewSheet, Name:="Flux Profile Diagram"

```

```

With ActiveChart
    .HasTitle = True
    .ChartTitle.Characters.Text = "Column Profile (Flux)" & Chr(10) & ITEXT
    .Axes(xlCategory, xlPrimary).HasTitle = True
    .Axes(xlCategory, xlPrimary).AxisTitle.Characters.Text = "stage number"
    .Axes(xlValue, xlPrimary).HasTitle = True
    .Axes(xlValue, xlPrimary).AxisTitle.Characters.Text = "flux (input unit)"
End With
With ActiveChart.Axes(xlCategory)
    .HasMajorGridlines = True
    .HasMinorGridlines = False
End With
With ActiveChart.Axes(xlValue)
    .HasMajorGridlines = True
    .HasMinorGridlines = False
End With
ActiveChart.Axes(xlValue).Select
Selection.TickLabels.NumberFormat = "0.00"
ActiveChart.ApplyDataLabels Type:=xlDataLabelsShowNone, LegendKey:=False

```

```

With ActiveChart.Axes(xlCategory)
    .MinimumScale = 1
    .MaximumScale = NST
    .MinorUnitIsAuto = True
    .MajorUnitIsAuto = True
    .Crosses = xlAutomatic
    .ReversePlotOrder = False
    .ScaleType = xlLinear
    .DisplayUnit = xlNone
End With

```

```

For Each ser In ActiveChart.SeriesCollection
    With ser.Border
        .ColorIndex = 57
        .Weight = xlMedium
        .LineStyle = xlContinuous
    End With
Next ser
Sheets("Product Streams").Select

' Mole Fraction Profile -----
-----

' add chart
Charts.Add
ActiveChart.ChartType = xlXYScatterLines
On Error Resume Next
For Each ser In ActiveChart.SeriesCollection
    ser.Delete
Next ser
On Error GoTo 0

' select chart data
undels = ActiveChart.SeriesCollection.Count
With ActiveChart

    ' Component mole fraction Curves
    For i = 1 To NK
        .SeriesCollection.NewSeries
        .SeriesCollection(undels + i).XValues = "=" & wsfp.Name & "!R" & CInt(5) & "C1:
R" & CInt(4 + NST) & "C1"
        .SeriesCollection(undels + i).Values = "=" & wsfp.Name & "!R" & CInt(5) & "C" &
CInt(4 + NK + i) & ": R" & CInt(4 + NST) & "C" & CInt(4 + NK + i)
        .SeriesCollection(undels + i).Name = "=" & wsfp.Name & "!R4C" & CInt(4 + NK +
i)
    Next i
End With
ActiveChart.Location Where:=xlLocationAsNewSheet, Name:="Mole Fraction Profile
Diagram"

With ActiveChart
    .HasTitle = True
    .ChartTitle.Characters.Text = "Column Profile (Mole Fraction)" & Chr(10) & ITEXT
    .Axes(xlCategory, xlPrimary).HasTitle = True
    .Axes(xlCategory, xlPrimary).AxisTitle.Characters.Text = "stage number"
    .Axes(xlValue, xlPrimary).HasTitle = True
    .Axes(xlValue, xlPrimary).AxisTitle.Characters.Text = "mole fraction"
End With
With ActiveChart.Axes(xlCategory)
    .HasMajorGridlines = True

```

```

    .HasMinorGridlines = False
End With
With ActiveChart.Axes(xlValue)
    .HasMajorGridlines = True
    .HasMinorGridlines = False
End With
ActiveChart.Axes(xlValue).Select
Selection.TickLabels.NumberFormat = "0.00"
ActiveChart.ApplyDataLabels Type:=xlDataLabelsShowNone, LegendKey:=False

With ActiveChart.Axes(xlCategory)
    .MinimumScale = 1
    .MaximumScale = NST
    .MinorUnitIsAuto = True
    .MajorUnitIsAuto = True
    .Crosses = xlAutomatic
    .ReversePlotOrder = False
    .ScaleType = xlLinear
    .DisplayUnit = xlNone
End With
With ActiveChart.Axes(xlValue)
    .MinimumScale = 0
    .MaximumScale = 1
    .MinorUnitIsAuto = True
    .MajorUnitIsAuto = True
    .Crosses = xlAutomatic
    .ReversePlotOrder = False
    .ScaleType = xlLinear
    .DisplayUnit = xlNone
End With

```

```

For Each ser In ActiveChart.SeriesCollection
    With ser.Border
        .ColorIndex = 57
        .Weight = xlMedium
        .LineStyle = xlContinuous
    End With
    Next ser

```

```

Sheets("Product Streams").Select
Range("A1").Select
With Selection.Font
    .Name = "Arial"
    .Size = 16
    .Strikethrough = False
    .Superscript = False

```

```
.Subscript = False  
.OutlineFont = False  
.Shadow = False  
.Underline = xlUnderlineStyleNone  
.ColorIndex = xlAutomatic
```

```
End With
```

```
Selection.Font.Bold = True  
Range("A3").Select
```

```
End Sub
```

```
Public Sub desw_prepare_sheets()  
' On Error Resume Next  
' Sheets("Flux Profile").Add  
' Sheets("Product Streams").Add  
' Sheets("desw_in").Add  
' On Error GoTo 0  
Sheets("desw_in").Select  
Cells.Select  
Selection.Clear
```

```
With ws
```

```
.Cells(1, 1) = "Distillation (Naphthali-Sandholm) Using the Wilson-Model"  
.Cells(2, 1) = "based on code given in 'Grundoperationen' (Gmehling, Brehm)"  
.Cells(4, 1) = "General Information"  
.Cells(5, 1) = "Number of components:"  
.Cells(6, 1) = "Title"  
.Cells(8, 1) = "Pure Component Data"  
.Cells(9, 1) = "Molar volume, Antoine constants (P [kPa] = 10^(A-B/(C+T[°C])))"  
.Cells(9, 2) = "vL"  
.Cells(9, 3) = "A"  
.Cells(9, 4) = "B"  
.Cells(9, 5) = "C"  
.Cells(16, 1) = "Interaction Parameters (Wilson, K)"  
.Cells(17, 2) = "1"  
.Cells(17, 3) = "2"  
.Cells(17, 4) = "3"  
.Cells(17, 5) = "4"  
.Cells(17, 6) = "5"  
.Cells(18, 1) = "1"  
.Cells(19, 1) = "2"  
.Cells(20, 1) = "3"  
.Cells(21, 1) = "4"  
.Cells(22, 1) = "5"  
.Cells(18, 2) = "0"  
.Cells(19, 3) = "0"  
.Cells(20, 4) = "0"  
.Cells(21, 5) = "0"  
.Cells(22, 6) = "0"  
.Cells(24, 1) = "Column Configuration (Stage 1 is the Reboiler)"
```

```
.Cells(25, 1) = "Number of stages (max. 50)"
.Cells(26, 1) = "Number of feeds"
.Cells(27, 1) = "Number of liquid side streams"
.Cells(28, 1) = "Number of vapor side streams"
.Cells(29, 1) = "Destillate flux"
.Cells(30, 1) = "Reflux ratio"
.Cells(31, 1) = "Top pressure (kPa)"
.Cells(32, 1) = "Bottom pressure (kPa)"
.Cells(33, 1) = "Top temperature estimate ( C)"
.Cells(34, 1) = "Bottom temperature estimate ( C)"
.Cells(35, 1) = "FLMAX"
.Cells(36, 1) = "DTMAX"
.Cells(37, 1) = "Exponent of convergence criterion"
.Cells(39, 1) = "Feeds"
.Cells(39, 2) = "stage"
.Cells(39, 3) = "q"
.Cells(39, 4) = "n1"
.Cells(39, 5) = "n2"
.Cells(39, 6) = "n3"
.Cells(39, 7) = "n4"
.Cells(39, 8) = "n5"
.Cells(40, 1) = "1"
.Cells(41, 1) = "2"
.Cells(42, 1) = "3"
.Cells(43, 1) = "4"
.Cells(44, 1) = "5"
.Cells(45, 1) = "6"
.Cells(46, 1) = "7"
.Cells(47, 1) = "8"
.Cells(48, 1) = "9"
.Cells(49, 1) = "10"
```

End With

```
Range("A1").Select
With Selection.Font
    .Name = "Arial"
    .Size = 16
    .Strikethrough = False
    .Superscript = False
    .Subscript = False
    .OutlineFont = False
    .Shadow = False
    .Underline = xlUnderlineStyleNone
    .ColorIndex = xlAutomatic
End With
```

```
Selection.Font.Bold = True
Range("A1:F1").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("A4:F4").Select
```

```
With Selection.Interior
    .ColorIndex = 33
    .Pattern = xlSolid
End With
Range("A8:F8").Select
With Selection.Interior
    .ColorIndex = 33
    .Pattern = xlSolid
End With
Range("A16:F16").Select
With Selection.Interior
    .ColorIndex = 33
    .Pattern = xlSolid
End With
Range("A24:F24").Select
With Selection.Interior
    .ColorIndex = 33
    .Pattern = xlSolid
End With
Range("A39:H39").Select
With Selection.Interior
    .ColorIndex = 33
    .Pattern = xlSolid
End With
Range("A5:A6").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("A9:A14").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("A17:A22").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("B17:F17").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("A25:A37").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("A40:A49").Select
With Selection.Interior
```

```
.ColorIndex = 34
.Pattern = xlSolid
End With
Range("B18:F22").Select
Selection.NumberFormat = "0.0000"
Range("B18").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("C19").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("D20").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("E21").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
Range("F22").Select
With Selection.Interior
    .ColorIndex = 34
    .Pattern = xlSolid
End With
ActiveWindow.ScrollRow = 1
Range("A1:F1").Select
Selection.Interior.ColorIndex = 37
Selection.Interior.ColorIndex = 33
Range("A2").Select
Selection.Font.Italic = True
Range("H7").Select
Columns("A:A").ColumnWidth = 27.89
Columns("B:I").Select
With Selection
    .HorizontalAlignment = xlCenter
    .VerticalAlignment = xlBottom
    .WrapText = False
    .Orientation = 0
    .AddIndent = False
    .ShrinkToFit = False
    .MergeCells = False
End With
Range("A10").Select
ActiveCell.FormulaR1C1 = "1"
Range("A11").Select
```

```
ActiveCell.FormulaR1C1 = "2"
Range("A12").Select
ActiveCell.FormulaR1C1 = "3"
Range("A13").Select
ActiveCell.FormulaR1C1 = "4"
Range("A14").Select
ActiveCell.FormulaR1C1 = "5"
Range("B15").Select
ActiveWindow.ScrollRow = 7
End Sub
```