
Table of Contents

Preface	XI
1 Historical review	1
References.....	13
2 Fundamentals of strain gage technology	17
2.1 Measurement principle and structure.....	17
2.1.1 Basic principles.....	17
2.1.2 Carrier material.....	30
2.1.3 Measuring grid material.....	32
2.2 Sensitivity.....	35
2.3 Transverse sensitivity	42
2.4 Temperature effects.....	47
2.4.1 Temperature effect on sensitivity.....	47
2.4.2 Thermal output of strain gages.....	49
2.5 Mechanics of the strain gage	55
2.5.1 Strain transfer from the measurement object to the measurement grid.....	55
2.5.2 Creep.....	57
2.5.3 Hysteresis.....	64
2.6 Influence of pressure	66
2.6.1 Hydrostatic pressure.....	66
2.6.2 Operation in a vacuum.....	72
2.7 Dynamic behaviour	74
2.7.1 First measurements using graphite layer strain gages.....	74
2.7.2 Fatigue strength.....	75
2.7.3 Shock load	80
2.7.4 Fatigue-life gage.....	82
2.8 Heat dissipation.....	84
2.9 Measuring at elevated temperatures	87
2.9.1 Previews.....	87
2.9.2 Weldable encapsulated tube strain gages.....	90
2.9.3 Free-filament strain gages.....	93
2.10 Stress gages	94
References.....	98
3 Installation of strain gages.....	109
3.1 Preparatory work	109
3.1.1 General preparation.....	109
3.1.2 Preparation of the strain gage	110
3.1.3 Preparation of the measurement point	110
3.2 Methods of fastening.....	112

3.2.1	Requirements	112
3.2.2	Cyanoacrylate	114
3.2.3	Methyl acrylate	116
3.2.4	Epoxy adhesives	117
3.2.5	Phenolic resin adhesives	119
3.2.6	Ceramic putty	120
3.2.7	Flame spraying	121
3.2.8	Spot welding	123
3.3	Different measurement object materials	124
3.3.1	Glass, enamel, glazed porcelain	124
3.3.2	Concrete	124
3.3.3	Wood	127
3.3.4	Plastics	129
3.4	Measurement point protection	134
3.5	Quality tests of the strain gage installation	140
	References	142
4	The Wheatstone bridge circuit	147
4.1	Circuit principle	147
4.2	Basic equation of the bridge circuit	147
4.3	Temperature compensation	152
4.4	Limit of the bridge signal resolution	155
4.5	Examples of some elementary bridge circuits	156
	References	162
5	Adjustment and compensation circuits	163
5.1	General	163
5.2	Compensation of zero shift with temperature change and zero adjustment	166
5.3	Compensation of temperature effects on the sensitivity and linearity measures	171
5.4	Adjustment of the characteristic value	176
5.5	Creep compensation	178
5.6	Full-bridge circuits connected in parallel	179
	References	182
6	Cable between the strain gage bridge circuit and measuring instrument	183
6.1	Basic	183
6.2	Ohmic resistance of the cable	183
6.2.1	Preliminary remarks	183
6.2.2	Ohmic resistance of the cable in full-bridge circuits	183
6.2.3	Ohmic resistance of the cable in half and quarter-bridge circuits	185
6.3	Influence of cable capacitance	187
6.3.1	Preliminary remarks	187
6.3.2	Capacitive asymmetry	188

6.3.3	Phase shift.....	189
6.3.4	Amplitude drop.....	191
6.4	Full-bridge connection in four-wire technology.....	193
6.5	Six-wire circuit.....	196
6.6	Dual-channel principle	197
6.7	Connection of half and quarter bridges.....	200
6.8	Protection against disturbing influences.....	204
6.8.1	Protection against electrical and magnetic fields.....	204
6.8.2	Electromagnetic compatibility.....	206
6.8.3	Protection against overvoltage	207
	References.....	210
7	Signal processing	211
7.1	Introductory viewing	211
7.2	Analogue instrumentation amplifier.....	212
7.2.1	Structure of analogue signal processing	212
7.2.2	Bridge supply with carrier frequency.....	214
7.2.3	Bridge supply with direct current	219
7.3	Digital amplifier concepts.....	222
7.3.1	Computer controlled analogue amplifier	222
7.3.2	New methods of analogue-to-digital conversion.....	223
7.3.3	Structure of digital measuring amplifier.....	225
7.4	Compensation method.....	228
7.5	Multipoint measurement	232
7.5.1	Preliminary remarks.....	232
7.5.2	Serial multipoint measurement.....	233
7.5.3	Parallel multipoint measurement.....	236
	References.....	239
8	Calibration of devices for measuring with strain gages	241
8.1	Introduction.....	241
8.2	Measurement chain.....	241
8.3	Characteristic and sensitivity.....	243
8.4	Calibration of the entire measurement chain as a measuring device.....	245
8.5	Compensators	246
8.6	Transducers	247
8.6.1	Transducers calibrated by the manufacturer	247
8.6.2	Calibrating transducers self-made by the user	248
8.7	Calibration measures	249
8.7.1	Calibration unit	249
8.7.2	Measurement amplifier with built-in calibration device	250
8.7.3	Shunt calibration.....	251
8.8	Calibration of measuring arrangements with self-installed strain gages.....	255
8.8.1	Wheatstone bridge circuit	255

8.8.2	Example of the calibration of a measuring device for measuring with self-installed strain gages.....	256
	References.....	257
9	Determination of mechanical stresses from strains measured with strain gages.....	259
9.1	Introduction.....	259
9.2	Terms of stress and strain	260
9.3	Elastic deformation and stress of a tensile rod under uniaxial tensile loading.....	262
9.4	The biaxial stress state.....	269
9.5	Mohr's circle.....	272
9.6	Deformation circle.....	277
9.7	Types of rosettes and grid notation.....	280
9.8	Evaluation formulas for 0/45/90° strain gage rosettes.....	281
9.9	Evaluation formulas for 0/60/120° strain gage rosettes.....	285
	References.....	288
10	Application examples of elastic deformation.....	289
10.1	Initial considerations	289
10.2	Principal directions are known	291
10.2.1	Examples of measurement objects loaded longitudinally.....	291
10.2.2	Measurement objects subject to bending loads	297
10.2.2.1	Initial consideration	297
10.2.2.2	Bending beam clamped at one end	298
10.2.2.3	Bending beam clamped at both ends.....	302
10.2.2.4	Bending beam freely supported at both ends	306
10.2.3	Measurement objects subject to torsion loads	308
10.2.4	Shear stresses in a beam.....	312
10.3	Stress analysis for unknown principal directions	319
10.3.1	Example of stress analysis using a 0/60/120° rosette	319
10.3.2	Loading of a shaft with superimposed torsion and bending.....	322
10.4	Simultaneous measurement of multiple load components.....	327
10.5	Diaphragm rosettes	334
10.5.1	Basics	334
10.5.2	Example of dimensioning a membrane for pressure measurements	338
	References.....	339
11	Determination of thermal stresses.....	343
11.1	Emergence of thermal stresses.....	343
11.2	Sensing the prevented thermal expansion at identical temperature at the compensation gage and the active strain gage.....	345
11.3	Determination of the restricted thermal expansion by computational correction of the measured values with previously measured thermal outputs on dummies.....	347

11.4	Determination of the restricted thermal expansion by mathematical correction with the thermal outputs determined at the original measurement object.....	349
11.5	The ‘reversible’ strain gage.....	349
11.6	Separation of the mechanical strain from the thermal strain	350
11.7	Compensated half-bridge strain gage with compensation resistor.....	352
	References.....	353
12	Strain gages as a means for experimental determination of residual stresses.....	355
12.1	Preliminary observation.....	355
12.2	Cutting-down method.....	357
12.3	Layer removal method	364
12.4	Ring-core method	371
12.4.1	Principle of the ring-core method	371
12.4.2	Application of the method.....	377
12.4.3	Electrical connection of the ring-core rosette	379
12.4.4	Practical application example.....	380
12.4.5	Multi-stage application of the ring-core method	388
12.4.6	Modified ring-core rosettes for smaller core diameters.....	391
12.5	Hole-drilling method.....	394
12.5.1	Introduction.....	394
12.5.2	Residual stress as an integrated mean value over the drilling depth.....	396
12.5.2.1	Introductory remarks	396
12.5.2.2	Stress distribution in the vicinity of a hole.....	397
12.5.2.3	Strains measured.....	400
12.5.2.4	Computation of the residual stress state	403
12.5.3	Determination of the residual stress distribution in relationship to the depth.....	404
12.5.4	Forming the hole.....	409
12.6	Bibliography.....	411
13	Stress analysis using strain gages in the elastoplastic deformation range	419
13.1	Introduction.....	419
13.2	Equivalent state with elastic deformation	420
13.3	Elastoplastic deformation.....	422
13.4	Stress analysis.....	423
13.5	Practical Example of application	425
13.6	Tensorial representation of the elastoplastic deformation.....	428
	References.....	431
14	Strength theories.....	433
14.1	Preview	433
14.2	Concept of effective stress	434

14.3	Experimental results	437
14.4	Maximum stress theory	441
14.5	Maximum shear theory	442
14.6	Extended shear theory	443
14.7	Plastic potential theory	444
14.8	Distortion energy (shape changing) theory	446
14.9	Octahedral plane shear stress theory	449
	References	450
	Index	451