

Correction remark for Table 13.1 on page 255

The results of newer investigations show that the “Minimum Ignition Pressures” noted in table 13.1 on page 255 is too high (see lit. ref. 8 in chapter 6 of this book).

We do reflect this fact in our current process and plant design.

Michael Jacob