

Index

a

Abnormal grain growth 18
 Acceptable welds/good welds 3, 19, 117, 120, 123–124
 Adhesive bonding 26
 Age-hardening alloys *see*
 Precipitation-hardening alloys
 Allotropic transformations 138
 Alloying (defined) 15
 Alpha case (in titanium alloys) 106
 Aluminum alloy cracking (due to welding) 103, 147
 Angular distortion/bowing 51
 Angular misalignment *see*
 Joint set-up problems
 Annealing (defined) 276
 Appearance *see* Weld appearance
 Arc blow 72
 Arc strike(s) 128, 129
 Atomic bonding
 covalent bonding 9, 10
 dipole bonding (*see*
 Secondary bonding)
 fluctuating dipole bonding (*see*
 Secondary bonding)
 induced dipole bonding (*see*
 Secondary bonding)
 ionic bonding 9, 10
 metallic bonding 9, 10
 mixed bonding 10
 permanent dipole bonding (*see*
 Secondary bonding)
 primary bonding 9, 10
 secondary bonding 9, 10
 van der Waals bonding 9, 10

Austenitic stainless steel *see*

 Stainless steels

Autogenous welding (defined) 148, 211, 302

b

Back-up bars, strips or tape
 (for welding) 34
 Backward problem-solving approach 5
 Bad welds *see*
 Unacceptable welds (bad welds)
 Baking welding electrodes 84
 Banded microstructure (in steels) 191
 Base metal(s)/base material(s) 25
 Beachmarks *see* Fatigue fracture features
 Bead-on-plate (BOP) welds 55
 Bead-shape-induced cracking *see*
 Centerline or longitudinal cracks
 Bevel angle 31
 Blind welds (partial-penetration welds)
 see Weld joint configurations
 Bowing *see* Angular distortion/bowing
 Brazing 10, 169, 311
 Buffer layers 203, 315
 Build-up layers *see* Multi-pass
 /Multiple-pass welding or welds
 Burn-through (defect) 34, 38, 121
 Buttering (butter layers) 191 *see also*
 Multi-pass/Multiple-pass
 welding or welds

c

Carbon equivalent (C_{eq}) 100, 180–182
 Carbon steels *see* Steels

- Casting 14
- Categorization of problems (in welding/welds) 7, 20
- Causes of porosity in welds
 - air/atmosphere contamination 82
 - contamination by defective equipment 82
 - contamination from base metal 83
 - contamination by improper welding procedure 82
 - contamination of joint elements 80–81
 - hydrocarbon contamination 81
 - tarnish layers 80–81
 - water contamination 81
 - zinc galvanize 81
- Centerline or longitudinal cracks *see* Hot cracks/hot cracking
- Ceramic welding 8
- CGHAZ/FGHAZ/ICHAZ 184–185, 262, 265
- Chemical compatibility/incompatibility 311–312
- Cladding (by welding) *see* Multi-pass/Multiple-pass welding or welds; Welding (defined)
- Classification (of welding processes) 12
- Close-packed crystal structure (of metals) 50
- Coalescence (defined) 9
- Co-based superalloys 267
- Cold cracks/cold cracking 150
 - cross cracking or check cracking 92, 95–96
 - hydrogen cracking (*see* Hydrogen-assisted/induced cracking)
 - root cracks/cracking 92, 98
 - toe cracks/cracking 92, 98
 - transverse cracks/cracking 92
 - underbead cracks/cracking 92, 98
- Cold work/cold working 273–276
- Cold-worked 274
- Cold worked metals and alloys
 - 278–281
 - effect of welding on 282
 - weld HAZ in 282
 - welding of 283–284
- Codes (welding codes) 69, 89
- Configuration of welds *see* Weld joint configurations
- Consistency (defined) 297–298
- Constitutional liquation cracking *see* Hot cracks/hot cracking
- Constitutional supercooling 305
- Constitution diagrams *see* DeLong (constitution) diagram, Schaeffler (constitution) diagram, WRC diagram
- Continuity (for creating a weld) *see* Metallic (or material) continuity
- Convection (in weld pools) *see* Weld pool convection (forces and effects)
- Convection forces (in welds) 153
- Cooling curves (solidification) 157
- Copper alloy cracking (due to welding) 103–104
- Corrosion cracks/cracking (due to welding) 102, 192
- Crack(s) (defined) 89, 143–144
 - cold cracks 91, 98, 150 (*see also* Cold cracks/cold cracking)
 - corrosion cracks 91
 - effect of cracks 90
 - fatigue cracks 91, 102 (*see also* Fatigue cracks/fatigue cracking)
 - hot cracks 91, 143–146 (*see also* Hot cracks/hot cracking)
- Crater cracks *see* Hot cracks/hot cracking
- Crater pipe (discontinuity) 68–69
- Cr-depleted zone (or Cr denuded zone) 249–250
- Creep 258–259
- Creep limit 260
- Creep-resistant PH alloys 258
- Crown bead *see* Weld crown bead/weld bead crown

CTE (effect of temperature) 58
 CTE mismatch 59, 315, 317
 CTEs of metals and alloys 316
 Cushion layers *see* Multi-pass/
 Multiple-pass welding or welds

d

Decohesion (defined) 260
 Defects (in welds) *see* Discontinuities
 Deformation-induced martensite 247
 Deformation processing 14
 Degree of dilution 303
 Delamination (defect) 191, 192
 Delayed cracking *see* Hydrogen-assisted
 or induced cracking
 DeLong (constitution) diagram 83, 106
 Diffusion welding *see* Non-fusion
 welding
 Digging arcs 118
 Dilution (in fusion welds) 150, 210,
 212, 302, 304, 312
 Dimensional shrinkage (in welding) 36
 thermal contraction 34–35
 volumetric shrinkage 34
 Discontinuities 35–36 *see also* Joint
 discontinuities
 Dislocations 15, 273–274
 edge dislocations 16
 mixed dislocations 16
 screw dislocations 16
 Dissimilar materials 309–310
 Dissimilar metal and alloy welding
 311
 Distortion (warpage) 29, 48, 57–58,
 60, 61
 Ductile-to-brittle transition and DBTT
 241–242
 Dynamic recrystallization (during hot
 working) 273

e

Effective liquidus temperature 157
 Effective solidus temperature 157
 Effects of gases in metals 76
 Effects of porosity *see* Porosity
 Elastic limit (defined) 274

Embrittling phases 287
 Environmentally-assisted cracking *see*
 Hydrogen-assisted or induced
 cracking

f

Failure to fit (defined) 19
 Failure to function (defined) 20
 Fatigue cracks/cracking (due to welding)
 102, 196
 Fatigue cracks/fatigue cracking 185
 Fatigue failure(s) 195–196
 Fatigue fracture features
 beachmarks 197
 striations 196, 198
 terminal overload area 197
 thumbnails origins 197
 Faying surfaces (defined) 221
 Fe-Cr phase diagram 248, 288
 Fe-Fe₃C phase diagram 129
 Ferritic alloy steels 260–261
 Filler metal(s) (defined) 302 *see also*
 matching/matched filters,
 overmatching or overmatch
 filter, undermatched or
 undermatching filter
 Fillet weld face/weld face 118
 Fillet welds 123
 Fisheyes (in hydrogen cracking) 99
 Fixturing (weldments) 61
 Flame-straightening (heat straightening)
 61–62
 Flux (defined) 110, 111
 Flux inclusions *see* Solid inclusions
 Foreign debris or inclusions *see* Solid
 inclusions
 Forging laps 191
 Fracture mechanics 70
 Fracture toughness 89
 Freezing range (of alloys) 50, 157
 Friction stir welding (FSW) 224–225
 excess flash 226–228
 heat-affected zone (HAZ) 225
 kissing bonds 226–228
 lazy-S defect 226–228
 nugget collapse 226–228

Friction stir welding (FSW) (*contd.*)
 oxide-induced defects 226–228
 ribbon flask 226–228
 stir zone 225
 surface galling 226–228
 thermomechanically-affected zone (TMAZ) 225
 tunnels (defects) 226–227
 unaffected zone 225
 Friction welding, *see* Non-fusion welding
 Full-penetration welds *see* Weld joint configurations
 Fusing (glass welding) 8
 Fusion welding 17

g

Gamma loop/ γ -loop *see* Fe-Cr phase diagram
 Gases found in various welding processes 79, 80
 Gas impurities *see* Impurities (in welds)
 Gas inclusions/gas porosity (in welds) 109
 Gas(es) in molten weld metal 73–76–79 141–142
 Germination *see* Abnormal grain growth
 Ghost boundaries (in the PMZ) 164
 Glass welding *see* Fusing
 Good welds *see* Acceptable welds/good welds
 Grain growth (after cold work and recrystallization) 273
 Growth structure in welds (control of) 125, 148–150

h

Hardenability (of steels) 100, 127
 Hard-facing *see* Multi-pass/Multiple-pass welding or welds, Welding
 Heat-affected zone (HAZ) 158, 169 discontinuities 170
 Heat flow (factors affecting) 159
 Heat input/weld heat input 141
 Heat solid (Portevin-Severin) 140

Heat-straightening *see* Flame straightening (heat straightening)
 Heat tint *see* Weld heat tint
 Heterogeneous (defined) 300
 Heterogeneous welding or filler 302
 High-alloy (tool or stainless steels) *see* Steel(s)
 High-energy-density welding 63
 High-frequency electromagnetic vibration (of welds) 305
 High-strength low-alloy (HSLA) steels 261
 Homogeneity (defined) 300
 Homogeneous welding 302
 Hot cracks/hot cracking 91, 147–148
 centerline cracks/cracking 93, 94, 144
 constitutional liquation cracking 93, 97, 163
 crater cracks/cracking 93–95, 144
 fusion-line cracks/cracking 93
 liquation cracking 93, 97, 162 (*see also* Constitutional liquid cracking)
 longitudinal cracks/cracking 93, 144
 reheat cracks/cracking 93, 181, 183–184
 strain-age cracking (reheat cracking) 5, 21, 92, 170, 183–187, 257, 258, 261, 267–270
 transverse cracks 144, 315
 Hot working (defined) 277
 Hybrid structures 305
 Hydrogen-assisted or induced cracking 99, 109, 182, 239
 Hydrogen embrittlement 99

i

Immiscibility 313
 Impurities (in welds) 307
 foreign-matter inclusions 307
 gas impurities 307
 non-metallic impurities 307
 Impurity elements 307 *see also* Residual stresses or locked-in stresses

Included (joint) angle 31
 Inclusions *see* Solid inclusions
 Incomplete or insufficient penetration
 see Discontinuities
 Ingel's equation for stress concentration 90
 Inhomogeneity (in welds) 300
 Integral mechanical attachment 310
 Intergranular corrosion 250
 Intergranular corrosion cracking 177
 Intergranular or interdendritic cracking 91, 92
 Intermetallic compound (defined) 288
 Interpass temperature(s) 262
 Iron-carbon phase diagram *see* Fe-Fe₃C phase diagram

j

Joint discontinuities
 cold seam (*see* Weld bead overlap)
 convexity (excessive) 39, 41
 excessive reinforcement 35, 39
 incomplete or insufficient penetration 35–37
 lack of fusion or incomplete fusion 36–38
 undercut 41–42
 underfill 38–39
 weld bead overlap (or cold seam) 39, 41, 42
 Joint efficiency (defined) 25
 Joint geometry *see* Weld joint types
 Joint permanency 1
 Joint set-up problems 25, 31
 angular misalignment 31–33
 linear misalignment (mismatch) 31, 32
 Joint types (welding) 13
 butt joints 13
 corner joints 13
 edge joints 13
 lap joints 13
 tee or T joints 13

k

Knife-line attack 252–253

l

Lack of fusion or incomplete fusion *see* Joint discontinuities
 Lamellar tearing 189, 190
 Larsen-Miller parameter (in creep) 259
 Limiting property 299
 Linear misalignment *see* Joint set-up problems
 Liquation cracks/cracking *see* Hot cracks/hot cracking
 Liquid-metal-induced embrittlement (LME) 313–314
 Liquidus temperature 50, 157
 Location of problems in welds *see* Problems in welds (defined), and Part 2
 Locked-in stresses *see* Residual stresses
 Longitudinal cracks/cracking *see* Hot cracks/hot cracking
 Longitudinal (residual) stresses *see* Residual stresses
 Low-alloy steels *see* Steel(s)
 Low-C grades of stainless steels *see* Stainless steels

m

Machining 14
 Macrosegregation (in welds) 152–153, 300, 312
 Manifestation of weld problems *see* Problems in welds (defined), and Part 1
 Martensite (ferrous) 100, 127–128, 150–151, 182
 Martensitic transformation *in steels 179
 Matching/matched filler 211, 302–303
 Material specificity of welding problems
 see Problems in welds (defined), and Part 3
 Mechanical fastening 26, 310
 Mechanical incompatibility 315
 Mechanical joining 310
 Mechanical stresses 47
 Medium-alloy steels *see* Steel(s)

- Melting point (defined) 50, 157
 - Melting temperature (defined) 157
 - Metallic (or material) continuity 9, 10, 169, 219
 - Metallic inclusions *see* Solid inclusions
 - Metallurgical notches (stress risers) 196
 - Microfissuring (in the PMZ) 165
 - Microsegregation (during solidification) 96, 152, 300
 - Microstructural zones (in welds) 13, 14, 17–18, 137–141
 - fusion zone (FZ) 17
 - heat-affected zone (HAZ) 17
 - partially-melted zone (PMZ) 18
 - unaffected base metal (UBM) 17
 - unmixed zone 137
 - weld zone (WZ) 17, 137
 - Mild steels *see* Steel(s)
 - Mismatch (joint) *see* Joint set-up problems
 - Modulus of elasticity for metals and alloys 316
 - Multi-pass/Multiple-pass welding or welds 203, 205
 - buffering layers (same as cushion layers)
 - build-up layers 203
 - buttering layers 203, 210
 - clad layers/cladding (by welding) 206, 211
 - cover pass 204
 - cushion layers 203
 - defects 207–211
 - fill pass 204
 - hard-facing 210
 - hot pass 204
 - overlapping heat effects and/or HAZs 213
 - property alteration 213
 - root pass 204
 - temper beads/temper bead technique 205–206, 214–215
 - transition layers 210, 211, 213
 - underlayers 203, 216
 - Mushy zone (MZ) 159
- n**
- Ni-based superalloys 267
 - Nickel alloy cracking (due to welding) 104
 - Nitrogen-enhanced alloys 85
 - Non-close-packed crystal structure (of metals) 50
 - Non-equilibrium 157
 - Non-fusion welding 10, 18–19, 26, 63, 219
 - advantages of 220
 - diffusion welding 220, 222–223
 - friction stir welding *see* Friction stir welding
 - friction welding 220, 222
 - pressure welding 210, 222
 - processes (various) 221
 - shortcomings of 220
 - solid-state deposition 223
 - worked zone (in pressure welds) 284
 - Non-metallic impurities *see* Impurities
 - Non-metallic inclusions *see* Solid inclusions
 - Non-uniform thermal contraction 58
- o**
- OEM (Original Equipment Manufacturing) welding 13
 - Offset (joint offset) *see* Joint set-up problems
 - Ordered phase(s) (defined) 288, 291
 - Overmatching or overmatch filler 25, 96, 302–303
 - Oxide inclusions *see* Solid inclusions
- p**
- Partially-melted zone (PMZ) 157–160
 - cold cracking (hydrogen-induced) 164–165
 - constitutional liquation cracking 161–164
 - hot cracking (conventional) 161
 - liquation cracking 162
 - microfissuring 165
 - Partial-penetration welds *see* Weld joint configurations

- Passivation/passivating layer 248
 - Peening (hammer or shot) *see* Stress relief, Mechanical
 - PH stainless steels *see* Stainless steels
 - Pipes (pipe defects in welds) 191
 - Plain carbon steels *see* Steel(s)
 - Planishing *see* Stress relief, mechanical
 - Plastic welding/polymer welding *see* Thermal bonding
 - Plug welding *see* Weld joint configurations
 - Porosity (origin) 67, 143
 - causes of porosity in welds 80
 - cavity (*see* Wormhole porosity)
 - cluster porosity 68, 72
 - crater pipe 68–69
 - distributed porosity (*see* Uniform porosity)
 - effects of 69–70
 - globular porosity (*see* Spherical porosity)
 - internal porosity 68, 143
 - linear porosity 68, 72
 - pipng porosity 68
 - random porosity (*see* Uniform porosity)
 - removal of porosity 83–84
 - sources of porosity 77–80
 - spherical porosity 68
 - subsurface (*see* Internal porosity above)
 - surface-breaking porosity 67–68, 143
 - uniform porosity 68, 70–72
 - wormhole porosity 68, 72–73
 - Post-weld heat-treatment (PWHT) 33, 60, 63, 91, 100–101, 183, 198, 243–244, 261, 262, 267
 - Precipitation-hardening alloys 171
 - aging response (curves) 173
 - heat treatment process 172
 - phase diagram (generic) 171
 - prerequisites for precipitation hardening 172
 - reversion/reversion zone 172
 - welding effect on microstructure 172–173
 - welding effect on properties 172–173
 - welding procedures for 174–176
 - Predictability (defined) 292
 - Preheat/preheating 96, 100, 182–183
 - Preheat temperatures 262
 - Pre-setting joint elements (to reduce distortion) 61
 - Pressure welding *see* Non-fusion welding
 - Problems in welding (categorization) 20
 - Problems in welds (defined) 19
 - location (*see* Part 2) 20
 - manifestation (*see* Part 1) 20
 - material specificity (*see* Part 3) 21
- q**
- Quench cracking 182, 287
- r**
- Recovery (after cold work) 273, 276
 - Recrystallization (after cold work) 273, 276–278
 - Recrystallization anneal 276
 - Recrystallization temperature(s) 278
 - Refractoriness (defined) 305
 - Reheat cracks/cracking *see* Hot cracks/hot cracking
 - Removing porosity *see* Porosity
 - Repair welding 13
 - Residual stresses (locked-in stresses) 33, 48, 54–57, 60–63
 - Reversion/reversion zone *see* Precipitation-hardening alloys
 - Ripple marks/weld ripple marks 118, 121, 124–126
 - Root bead *see* Weld root bead
 - Root-bead suck-back *see* Suck-back
 - Root cause (defined) 80
 - Root face 31
 - Root gap 31, 33

S

- Schaeffler (constitution) diagram 83, 106, 293
- Secondary bonding 10
- Secondary hardening (in steels) *see* Steel(s)
- Second-phase strengthening 171
- Segregation-induced cracking *see* Centerline under Hot cracks
- Sensitization (in stainless steels) 101, 177, 249, 252
- Sensitization cracks/cracking (in SS) 101
- Sensitization range 177, 249
- Shape welding 207
- Shrinkage (during welding) *see* Dimensional shrinkage
- Shrinkage cavities 191
- Sievert's law (of gas solubility in welds) 73, 142
- Sigma (σ) phase 287–290
 - appearance in microstructure 290
 - avoiding 293, 294
 - effects of 291
 - Gow and Harder ratio factor prediction 293
 - Hull Creq prediction 294
 - identification 293
 - kinetics of formation 290–291, 293
 - morphologies 289
 - susceptibility 291, 292
 - susceptible alloys 291–293
 - unit cell 289
 - Woodyatt electron vacancy number prediction 294
- Slag (defined) 111
- Slag inclusions *see* Solid inclusions
- Slot welds *see* Weld joint configurations
- Slumping (weld slumping) 34
- Soldering 10, 169, 311
- Solidification (defined) 52
- Solidification growth (in welds) *see* Growth structure in welds
- Solid inclusions 109, 151
 - flux inclusions 109, 112
 - foreign debris 109
 - metallic inclusions 109, 114, 151, 152
 - non-metallic inclusions 109, 110, 151, 185
 - oxide inclusions 109, 113–114
 - slag inclusions 109, 112–113, 151–152
 - sulfide inclusions 114
- Solid metal embrittlement 313
- Solid-state deposition welding *see* Non-fusion welding
- Solidus temperature 50, 157
- Solute partitioning (during solidification) 300
- Splatter 118, 126, 127
- Stabilized grades of stainless steels 101–102, 179, 251
- Stainless steels 247
 - austenitic Mn-steels (Hadfield steels) 247, 266
 - austenitic stainless steels 249
 - knife-line attack 252–253
 - low-C grades 251
 - PH stainless steels 263, 266
 - sensitization (*see* Sensitization)
 - solutionizing treatment/solution anneal 252
 - stabilized grades 251
 - weld decay 21, 177, 179, 247–254
 - start and stop tabs (for welding) *see* Tabs
- Stainless steel cracking (due to welding) 105–106
- Steel(s) 235–237
 - blue brittleness (temper embrittlement) 240
 - carbon (plain C or mild) steels 238
 - embrittlement of 238, 239
 - forms of product 237
 - high-alloy steels 238, 247
 - hydrogen cracking of (*see* Hydrogen-assisted or induced cracking)
 - low-and medium-alloy steels 238
 - residual stress effects in 243
 - secondary hardening 240

- stainless steels 239
 - temper embrittlement (blue brittleness) 240
 - tool steels 239
 - varieties of 237
 - Steel cracking (due to welding) 104–105
 - Strain-age cracking 257, 267–269 *see also* Hot cracks/hot cracking
 - Strain-hardening (also work-hardening) 274–275
 - Strengthening mechanisms 14–17, 170
 - Stress concentration 90
 - Stress corrosion cracking (SCC) 190, 193–195
 - Stress raiser(s)/stress riser(s) 89–90, 196
 - Stress relaxation cracking 257, 265
 - Stress relief, mechanical 198–199
 - Stress relief, thermal (after welding) *see* Post-weld heat treatment
 - Stress relief cracking 257, 262–264
 - Striations *see* Fatigue fracture features
 - Stringers (non-metallic) 189, 190
 - Structure-property-processing interrelationship 14 213
 - Sub-solidus liquation cracking 161
 - Suck-back 39
 - Sulfide inclusions *see* Solid inclusions
 - Sugaring 122
 - Superalloys 267
 - Surface profile-induced cracking *see* Centerline under Hot cracks
 - Surface welding *see* Welding (defined); Weld joint configurations
- t**
- Tabs (welding start and stop tabs) 54, 95
 - Tack welding/tack welds/tacking 34–35, 61, 62
 - Taxonomy (of welding processes) *see* Classification
 - Temper beads/Temper bead technique *see* Multi-pass/Multiple-pass welding or welds
 - Temper colors (heat tint) 129
 - Temper embrittlement 240
 - Tempering 18, 240–2413
 - Terminal overload area *see* Fatigue fracture features
 - Thermal bonding (plastic welding) 7, 8, 311
 - Thermal incompatibility 315, 317
 - Thermally-induced stresses 47, 52, 185
 - due to CTE mismatch 52
 - due to thermal expansion/contraction 47, 185
 - due to volumetric shrinkage 47, 48, 51, 52, 185
 - Thermal stress relief *see* Post-weld heat treatment
 - Thermophysical properties (of materials) 51, 59
 - Thumbnail origins *see* Fatigue fracture features
 - Titanium alloy cracking (due to welding) 106
 - Toughness (defined) 273
 - Transition layers *see* Multi-pass/Multiple-pass welding or welds
 - Transition pieces (for dissimilar welding) 317
 - Transverse (residual) stresses *see* Residual stresses
 - Troubleshooting 5, 20
 - Types of weld joints *see* Weld joint types
 - Types of welds *see* Weld types
- u**
- Ultrasonic vibration (of welds) 305
 - Unacceptable welds (bad welds) 1, 3, 19, 117, 120, 123–124
 - Unaffected base metal (UBM) 189
 - Undermatched or undermatching filler 302–303
 - Uniformity (definition) 298–299
 - Unmixed zone (UMZ) 304–306

W

Warpage *see* Distortion (warpage)

Weakest link concept 298–299

Weld (defined) 19

Weldability(defined) 102

Weld appearance 117

Weld contour 118

Weld cracks *see* Cracks (defined)

Weld crown bead/weld bead crown
118, 119

Weld decay *see* Sensitization in stainless
steel

Weld dilution *see* Dilution (in fusion
welds)

Weld heat input *see* Heat input/weld
heat input

Weld heat tint 129–131

Welding (defined) 7, 9, 13

clad welding 13

fusion welding (*see* Fusion welding)

hard-facing 13

non-fusionwelding (*see* Non-fusion
welding)

OEM welding 13

pressure welding (*see* Non-fusion
welding)

repair welding 13

surface welding 13, 27–28

Weld joint configurations 27–28

bevel grooves/bevel welds 29, 30

blind welds (partial-penetration
welds) 27

full-penetration welds 27

groove welds 28

J-grooves 30

K-joints 30

partial-penetration welds (blind
welds) 27

plug welds 27–28

slot welds 28

square/straight butt welds 28, 30

U-grooves (single or double) 30

V-grooves (single or double) 30

Weld joint problems 25

Weld joint types 27

Weldment (defined) 19

Weld pool convection (forces and
effects) 84–85, 301

Weld profile (weld shape) 31, 35, 40,
41, 119

Weld ripple marks *see* Ripple
marks/weld ripple marks

Weld root bead/weld root 121

Weld shape *see* Weld profile (weld
shape)

Weld spatter *see* Spatter

Weld types 13

Weld width 118

Weld zone (WZ) *see* Microstructural
zones (in welds)

Worked zone (in pressure welds) 284

Work-hardening (also strain hardening)
273–274

WRC diagram 83

Wrought (products and microstructure)
25

y

Yield point, Upper-and Lower-(in steels)
279

z

Zones (of microstructure in welds) *see*
Microstructural zones (in welds)