

## Contents

### Preface *xi*

- 1 Introduction 1**
  - Further Reading 6
- 2 Categorization of Welding and Weld Problems 7**
  - 2.1 What Is Welding? 7
  - 2.2 Microstructural Zones of Welds 13
  - 2.3 Origin of Problems in Welding and Welds 19
  - 2.4 How Problems Can Be Logically Categorized? 20
  - References 21
  - Further Reading 21

### Part I Manifestation of Problems with Welds and Weldments 23

- 3 Problems with Joint Setup and Weld Joints 25**
  - 3.1 Joint Efficiency 25
  - 3.2 Weld Joint Types and Weld Configurations 26
  - 3.3 Joint Setup Problems 31
  - 3.4 Problems with Weld Profile 35
  - 3.5 Troubleshooting Guide 42
  - References 45
  - Further Reading 45
- 4 Shape Distortion, Dimensional Shrinkage, and Geometric Instability 47**
  - 4.1 Thermal Versus Mechanical Stresses in a Structure 47
  - 4.2 Residual Stresses Versus Distortion 48
  - 4.3 Origin and Effect of Volumetric Shrinkage 48
  - 4.4 Origin and Effect of Thermal Contraction 52
  - 4.5 Problems from Nonuniform Thermal Contraction and CTE Mismatches 57

4.6	Problems from Distortion and from Residual Stresses	60
4.7	Distortion Control and Residual Stress Reduction	60
4.8	Troubleshooting Guide	65
	References	65
	Further Reading	66
<b>5</b>	<b>Porosity</b>	<b>67</b>
5.1	The Most Common Problem in Welds	67
5.2	Types of Weld Porosity	70
5.3	Gases in Molten Weld Metal	73
5.4	The Many Possible Causes of Porosity in Welds	79
5.5	Attempting to Minimize Porosity Formation in Fusion Welds	84
5.6	Troubleshooting Porosity Problems in Welds	85
	References	87
	Further Reading	87
<b>6</b>	<b>Cracks</b>	<b>89</b>
6.1	The Most Dreaded Defect in Welds	89
6.2	Classification of Cracking and Cracks in Welds and Welding	90
6.3	Hot Cracking and Cracks	91
6.4	Cold Cracking and Cracks	98
6.5	Other Weld-Related Cracking and Cracks	101
6.6	Crack-Prone Metals and Alloys	102
6.7	Troubleshooting Cracking Problems in Welds	105
	References	106
	Further Reading	107
<b>7</b>	<b>Nonmetallic and Metallic Inclusions</b>	<b>109</b>
7.1	Solid Versus Gas Inclusions	109
7.2	Nonmetallic Inclusions in Welds	110
7.3	Metallic Inclusions in Welds	114
7.4	Troubleshooting Problems with Inclusions in Welds	115
	References	116
	Further Reading	116
<b>8</b>	<b>Weld Appearance</b>	<b>117</b>
8.1	Can You Judge a Book by Its Cover? Is Beauty Only Skin Deep?	117
8.2	Weld Crown Bead Faults	118
8.3	Weld Root Bead Faults	121
8.4	Fillet Weld Faults	123
8.5	Reading Weld Ripple Marks	124
8.6	Weld Spatter	126
8.7	Arc Strikes	128
8.8	Weld Heat Tint	129
8.9	Troubleshooting Weld Appearance Problems	132
	References	133
	Further Reading	134

**Part II Location of Problems in Welds 135**

- 9 Fusion Zone of Fusion Welds 137**
  - 9.1 A Refresher on Microstructural Zones in and Around Welds 137
  - 9.2 Gas Porosity in the Fusion Zone of Welds 141
  - 9.3 Cracking in the Fusion Zone of Welds 143
  - 9.4 Inclusions in the Fusion Zone of Welds 151
  - 9.5 Macrosegregation in the Fusion Zone of Welds 152
  - 9.6 Troubleshooting Problems in the Fusion Zone of Welds 153
  - References 155
  - Further Reading 156
- 10 Partially Melted Zone of Fusion Welds 157**
  - 10.1 Origin and Location of the PMZ in Fusion Welds 157
  - 10.2 Conventional Hot Cracking in the PMZ 161
  - 10.3 Constitutional Liquation Cracking in the PMZ 161
  - 10.4 Cold Cracking in the PMZ 164
  - 10.5 Overcoming Cracking Problems in the PMZ 166
  - 10.6 Troubleshooting Problems in the PMZ 167
  - References 167
  - Further Reading 168
- 11 Heat-Affected Zone of Fusion Welds 169**
  - 11.1 Origin and Location of the HAZ for Fusion Welds 169
  - 11.2 Manifestation of Problems in the HAZ of Fusion Welds 170
  - 11.3 Precipitation-Hardening Alloy HAZ Problems 171
  - 11.4 Sensitization in the HAZ of Austenitic Stainless Steels 176
  - 11.5 Transformation-Hardening Steel HAZ Problems 179
  - 11.6 Reheat Cracking 183
  - 11.7 Troubleshooting Problems in the HAZ of Fusion Welds 186
  - References 187
  - Further Reading 188
- 12 Unaffected Base Metal Cracking Associated with Welding 189**
  - 12.1 Weld-Related Problems in the Unaffected Base Metal 189
  - 12.2 Lamellar Tearing in Thick Steel Weldments 189
  - 12.3 Corrosion Cracking Caused by Fusion Welding 192
  - 12.4 Fatigue Cracking Outside Fusion Welds 195
  - 12.5 Troubleshooting Weld-Related Problems in the Unaffected Base Metal 199
  - References 200
  - Further Reading 201
- 13 Discontinuities in Multi-pass Welds 203**
  - 13.1 Needs for Multi-pass Welding and Welds 203
  - 13.2 Various Functions of Multi-pass Welding and Welds 205

- 13.3 Defects Found in Multi-pass Welds 207
- 13.4 Composition Adjustment with Multi-pass Welding 210
- 13.5 Property Alteration with Multi-pass Welding 213
- 13.6 Troubleshooting Problems in Multi-pass Welding and Welds 216
  - References 217
  - Further Reading 217

#### **14 Problems with Non-fusion Welding and Non-fusion Welds 219**

- 14.1 Non-fusion Welding Processes Versus Fusion Welding Processes 219
- 14.2 Overview of Non-fusion Processes 220
  - 14.2.1 Pressure Welding Processes 222
  - 14.2.2 Friction Welding Processes 222
  - 14.2.3 Diffusion Welding Processes 222
  - 14.2.4 Solid-State Deposition Welding 223
- 14.3 Problems with Non-fusion Welds and Non-fusion Welding Processes 223
- 14.4 Inspection and Repair Challenges with Non-fusion Welds 229
- 14.5 Troubleshooting Problems with Non-fusion Welds 230
  - References 230
  - Further Reading 231

### **Part III Material-Specific Weld-Related Problems 233**

#### **15 Embrittlement of Carbon and Low- and Medium-alloy Steels 235**

- 15.1 The Importance of Steel 235
- 15.2 Four Causes of Embrittlement in Carbon and Low- and Medium-alloy Steels 238
- 15.3 Hydrogen Embrittlement: A Misnomer in Steels 239
- 15.4 Secondary Hardening in Steels 240
- 15.5 Ductile-to-Brittle Transition in Steels 241
- 15.6 Compromise of Fatigue and Impact Behavior by Residual Stresses in Steels 243
- 15.7 Troubleshooting Problems from Embrittlement of Steels by Welding 244
  - References 245
  - Further Reading 245

#### **16 Sensitization or Weld Decay and Knife-line Attack in Stainless Steels 247**

- 16.1 A Primer on the Metallurgy of Stainless Steels 247
- 16.2 Sensitization of Austenitic Stainless Steels by Welding 249
- 16.3 Sensitization of Other Grades of Stainless Steel 252

16.4	Knife-line Attack in Stabilized Austenitic Stainless Steels	252
16.5	Troubleshooting Problems from Sensitization or Knife-line Attack	254
	References	255
	Further Reading	255
<b>17</b>	<b>Stress Relief Cracking of Precipitation-Hardening Alloys</b>	<b>257</b>
17.1	Different Names, Same Phenomenon	257
17.2	Stress Relief Cracking in Ferritic Alloy Steels	260
17.3	Stress Relaxation Cracking in Stainless Steels	265
17.4	Strain-age Cracking in Ni-Based Superalloys	267
17.5	Troubleshooting Problems from Stress Relief or Strain-age Cracking	270
	References	271
	Further Reading	271
<b>18</b>	<b>Loss of Properties in Cold-Worked Metals and Alloys</b>	<b>273</b>
18.1	Cold Work, Recovery, Recrystallization, and Grain Growth	273
18.2	Cold-Worked Metals and Alloys in Engineering	278
18.3	Avoiding or Recovering Properties Loss from Fusion Welding	281
18.4	The Worked Zone in Pressure-Welded Metals and Alloys	284
18.5	Troubleshooting Welding Problems in Cold-Worked Metals and Alloys	285
	References	285
	Further Reading	286
<b>19</b>	<b>Embrittlement with High-chromium Contents</b>	<b>287</b>
19.1	Phase Formation and Structure	287
19.2	Adverse Effects of $\sigma$ -Phase	291
19.3	Susceptible Alloys	291
19.4	Guidelines for Avoiding or Resolving Problems from $\sigma$ -Phase	293
19.5	Troubleshooting Problems with $\sigma$ -Phase Associated with Welding	294
	References	295
	Further Reading	295
<b>20</b>	<b>Weld Dilution and Chemical Inhomogeneity</b>	<b>297</b>
20.1	The Designer's Druthers	297
20.2	Chemical Inhomogeneity in Welds	300
20.3	Weld Dilution	302
20.4	The Unmixed Zone in the Weld Metal	304
20.5	Impurities in the Weld Metal	307
20.6	Troubleshooting Problems from Weld Dilution and Chemical Inhomogeneity	307
	References	308
	Further Reading	308

<b>21</b>	<b>Dissimilar Metal and Alloy Welding</b>	<b>309</b>
21.1	Joining Dissimilar Materials	309
21.2	The Need for Welding Dissimilar Metals and Alloys	311
21.3	Chemical Incompatibility	311
21.4	Mechanical Incompatibility	315
21.5	Thermal Incompatibility	315
21.6	Troubleshooting Problems with Dissimilar Metal and Alloy Welding	318
	References	318
	Further Reading	319
	<b>Closing Thoughts</b>	<b>321</b>
	<b>Index</b>	<b>323</b>