

Contents

Preface *XI*

List of Symbols and Acronyms *XV*

1	Digital Linear Systems	1
1.1	Introduction to Digital Phase Demodulation in Optical Metrology	1
1.1.1	Fringe Pattern Demodulation as an Ill-Posed Inverse Problem	1
1.1.2	Adding <i>a priori</i> Information to the Fringe Pattern: Carriers	3
1.1.3	Classification of Phase Demodulation Methods in Digital Interferometry	7
1.2	Digital Sampling	9
1.2.1	Signal Classification	9
1.2.2	Commonly Used Functions	11
1.2.3	Impulse Sampling	13
1.2.4	Nyquist–Shannon Sampling Theorem	14
1.3	Linear Time-Invariant (LTI) Systems	14
1.3.1	Definition and Properties	15
1.3.2	Impulse Response of LTI Systems	15
1.3.3	Stability Criterion: Bounded-Input Bounded-Output	17
1.4	Z-Transform Analysis of Digital Linear Systems	18
1.4.1	Definition and Properties	18
1.4.2	Region of Convergence (ROC)	19
1.4.3	Poles and Zeros of a Z-Transform	20
1.4.4	Inverse Z-Transform	21
1.4.5	Transfer Function of an LTI System in the Z-Domain	22
1.4.6	Stability Evaluation by Means of the Z-Transform	23
1.5	Fourier Analysis of Digital LTI Systems	24
1.5.1	Definition and Properties of the Fourier Transform	25
1.5.2	Discrete-Time Fourier Transform (DTFT)	25
1.5.3	Relation Between the DTFT and the Z-Transform	26
1.5.4	Spectral Interpretation of the Sampling Theorem	27
1.5.5	Aliasing: Sub-Nyquist Sampling	29
1.5.6	Frequency Transfer Function (FTF) of an LTI System	31
1.5.7	Stability Evaluation in the Fourier Domain	33

1.6	Convolution-Based One-Dimensional (1D) Linear Filters	34
1.6.1	One-Dimensional Finite Impulse Response (FIR) Filters	34
1.6.2	One-Dimensional Infinite Impulse Response (IIR) Filters	37
1.7	Convolution-Based two-dimensional (2D) Linear Filters	39
1.7.1	Two-Dimensional (2D) Fourier and Z-Transforms	39
1.7.2	Stability Analysis of 2D Linear Filters	40
1.8	Regularized Spatial Linear Filtering Techniques	42
1.8.1	Classical Regularization for Low-Pass Filtering	42
1.8.2	Spectral Response of 2D Regularized Low-Pass Filters	46
1.9	Stochastic Processes	48
1.9.1	Definitions and Basic Concepts	48
1.9.2	Ergodic Stochastic Processes	51
1.9.3	LTI System Response to Stochastic Signals	52
1.9.4	Power Spectral Density (PSD) of a Stochastic Signal	52
1.10	Summary and Conclusions	54
2	Synchronous Temporal Interferometry	57
2.1	Introduction	57
2.1.1	Historical Review of the Theory of Phase-Shifting Algorithms (PSAs)	57
2.2	Temporal Carrier Interferometric Signal	60
2.3	Quadrature Linear Filters for Temporal Phase Estimation	62
2.3.1	Linear PSAs Using Real-Valued Low-Pass Filtering	64
2.4	The Minimum Three-Step PSA	68
2.4.1	Algebraic Derivation of the Minimum Three-Step PSA	68
2.4.2	Spectral FTF Analysis of the Minimum Three-Step PSA	69
2.5	Least-Squares PSAs	71
2.5.1	Temporal-to-Spatial Carrier Conversion: Squeezing Interferometry	73
2.6	Detuning Analysis in Phase-Shifting Interferometry (PSI)	74
2.7	Noise in Temporal PSI	80
2.7.1	Phase Estimation with Additive Random Noise	82
2.7.2	Noise Rejection in N -Step Least-Squares (LS) PSAs	85
2.7.3	Noise Rejection of Linear Tunable PSAs	86
2.8	Harmonics in Temporal Interferometry	87
2.8.1	Interferometric Data with Harmonic Distortion and Aliasing	88
2.8.2	PSA Response to Intensity-Distorted Interferograms	91
2.9	PSA Design Using First-Order Building Blocks	95
2.9.1	Minimum Three-Step PSA Design by First-Order FTF Building Blocks	97
2.9.2	Tunable Four-Step PSAs with Detuning Robustness at $\omega = -\omega_0$	100
2.9.3	Tunable Four-Step PSAs with Robust Background Illumination Rejection	101
2.9.4	Tunable Four-Step PSA with Fixed Spectral Zero at $\omega = \pi$	102
2.10	Summary and Conclusions	104

3	Asynchronous Temporal Interferometry	107
3.1	Introduction	107
3.2	Classification of Temporal PSAs	108
3.2.1	Fixed-Coefficients (Linear) PSAs	108
3.2.2	Tunable (Linear) PSAs	108
3.2.3	Self-Tunable (Nonlinear) PSAs	109
3.3	Spectral Analysis of the Carré PSA	110
3.3.1	Frequency Transfer Function of the Carré PSA	112
3.3.2	Meta-Frequency Response of the Carré PSA	113
3.3.3	Harmonic-Rejection Capabilities of the Carré PSA	114
3.3.4	Phase-Step Estimation in the Carré PSA	116
3.3.5	Improvement of the Phase-Step Estimation in Self-Tunable PSAs	118
3.3.6	Computer Simulations with the Carré PSA with Noisy Interferograms	120
3.4	Spectral Analysis of Other Self-Tunable PSAs	122
3.4.1	Self-Tunable Four-Step PSA with Detuning-Error Robustness	123
3.4.2	Self-Tunable Five-Step PSA by Stoilov and Dragostinov	126
3.4.3	Self-Tunable Five-Step PSA with Detuning-Error Robustness	128
3.4.4	Self-Tunable Five-Step PSA with Double Zeroes at the Origin and the Tuning Frequency	130
3.4.5	Self-Tunable Five-Step PSA with Three Tunable Single Zeros	131
3.4.6	Self-Tunable Five-Step PSA with Second-Harmonic Rejection	133
3.5	Self-Calibrating PSAs	136
3.5.1	Iterative Least-Squares, the Advanced Iterative Algorithm	137
3.5.2	Principal Component Analysis	140
3.6	Summary and Conclusions	145
4	Spatial Methods with Carrier	149
4.1	Introduction	149
4.2	Linear Spatial Carrier	149
4.2.1	The Linear Carrier Interferogram	149
4.2.2	Instantaneous Spatial Frequency	152
4.2.3	Synchronous Detection with a Linear Carrier	155
4.2.4	Linear and Nonlinear Spatial PSAs	159
4.2.5	Fourier Transform Analysis	164
4.2.6	Space-Frequency Analysis	170
4.3	Circular Spatial Carrier	173
4.3.1	The Circular Carrier Interferogram	173
4.3.2	Synchronous Detection with a Circular Carrier	174
4.4	2D Pixelated Spatial Carrier	177
4.4.1	The Pixelated Carrier Interferogram	177
4.4.2	Synchronous Detection with a Pixelated Carrier	180
4.5	Regularized Quadrature Filters	186

4.6	Relation Between Temporal and Spatial Analysis	198
4.7	Summary and Conclusions	198
5	Spatial Methods Without Carrier	201
5.1	Introduction	201
5.2	Phase Demodulation of Closed-Fringe Interferograms	201
5.3	The Regularized Phase Tracker (RPT)	204
5.4	Local Robust Quadrature Filters	215
5.5	2D Fringe Direction	216
5.5.1	Fringe Orientation in Interferogram Processing	216
5.5.2	Fringe Orientation and Fringe Direction	219
5.5.3	Orientation Estimation	222
5.5.4	Fringe Direction Computation	225
5.6	2D Vortex Filter	229
5.6.1	The Hilbert Transform in Phase Demodulation	229
5.6.2	The Vortex Transform	230
5.6.3	Two Applications of the Vortex Transform	233
5.7	The General Quadrature Transform	235
5.8	Summary and Conclusions	239
6	Phase Unwrapping	241
6.1	Introduction	241
6.1.1	The Phase Unwrapping Problem	241
6.2	Phase Unwrapping by 1D Line Integration	244
6.2.1	Line Integration Unwrapping Formula	244
6.2.2	Noise Tolerance of the Line Integration Unwrapping Formula	246
6.3	Phase Unwrapping with 1D Recursive Dynamic System	250
6.4	1D Phase Unwrapping with Linear Prediction	251
6.5	2D Phase Unwrapping with Linear Prediction	255
6.6	Least-Squares Method for Phase Unwrapping	257
6.7	Phase Unwrapping Through Demodulation Using a Phase Tracker	258
6.8	Smooth Unwrapping by Masking out 2D Phase Inconsistencies	262
6.9	Summary and Conclusions	266
	Appendix A List of Linear Phase-Shifting Algorithms (PSAs)	271
A.1	Brief Review of the PSAs Theory	271
A.2	Two-Step Linear PSAs	274
A.2.1	Two-Step PSA with a First-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	274
A.3	Three-Step Linear PSAs	275
A.3.1	Three-Step Least-Squares PSA ($\omega_0 = 2\pi/3$)	275
A.3.2	Three-Step PSA with First-Order Zeros at $\omega = \{0, -\omega_0\}$ ($\omega_0 = \pi/2$)	276
A.4	Four-Step Linear PSAs	277
A.4.1	Four-Step Least-Squares PSA ($\omega_0 = 2\pi/4$)	277

A.4.2	Four-Step PSA with a First-Order Zero at $\omega = 0$ and a Second-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	278
A.4.3	Four-Step PSA with First-Order Zeros at $\omega = \{0, -\omega_0/2, -\omega_0\}$ ($\omega_0 = \pi/2$)	279
A.4.4	Four-Step PSA with a First-Order Zero at $-\omega_0$ and a Second-Order Zero at $\omega = 0$ ($\omega_0 = \pi/2$)	280
A.4.5	Four-Step PSA with a First-Order Zero at $\omega = 0$ and a Second-Order Zero at $-\omega_0$ ($\omega_0 = 2\pi/3$)	281
A.5	Five-Step Linear PSAs	282
A.5.1	Five-Step Least-Squares PSA ($\omega_0 = 2\pi/5$)	282
A.5.2	Five-Step PSA with First-Order Zeros at $\omega = \{0, \pm 2\omega_0\}$ and a Second-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	283
A.5.3	Five-Step PSA with Second-Order Zeros at $\omega = \{0, -\omega_0\}$ ($\omega_0 = 2\pi/3$)	284
A.5.4	Five-Step PSA with Second-Order Zeros at $\omega = \{0, -\omega_0\}$ ($\omega_0 = \pi/2$)	285
A.5.5	Five-Step PSA with a First-Order Zero at $\omega = 0$ and a Third-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	286
A.5.6	Five-Step PSA with a First-Order Zero at $\omega = 0$ and a Third-Order Zero at $-\omega_0$ ($\omega_0 = 2\pi/3$)	287
A.6	Six-Step Linear PSAs	288
A.6.1	Six-Step Least-Squares PSA ($\omega_0 = 2\pi/6$)	288
A.6.2	Six-Step PSA with First-Order Zeros at $\{0, \pm 2\omega_0\}$ and a Third-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	289
A.6.3	Six-Step PSA with a First-Order Zero at $\omega = 0$ and a Fourth-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	290
A.6.4	Six-Step PSA with a First-Order Zero at $\omega = 0$ and Second-Order Zeros at $\{-\omega_0, \pm 2\omega_0\}$ ($\omega_0 = \pi/2$)	291
A.6.5	Six-Step (5LS + 1) PSA with a Second-Order Zero at $-\omega_0$ ($\omega_0 = 2\pi/5$)	292
A.7	Seven-Step Linear PSAs	293
A.7.1	Seven-Step Least-Squares PSA ($\omega_0 = 2\pi/7$)	293
A.7.2	Seven-Step PSA with First-Order Zeros at $\{0, -\omega_0, 2\omega_0, \pm 3\omega_0\}$ and a Second-Order Zero at $-2\omega_0$ ($\omega_0 = 2\pi/6$)	294
A.7.3	Seven-Step PSA with First-Order Zeros at $\{0, -\omega_0, 2\omega_0\}$ and a Second-Order Zero at $\pm 3\omega_0$ ($\omega_0 = 2\pi/6$)	295
A.7.4	Seven-Step PSA with First-Order Zeros at $\{0, \pm 2\omega_0\}$ and a Fourth-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	296
A.7.5	Seven-Step PSA with Second-Order Zeros at $\{0, -\omega_0, \pm 2\omega_0\}$ ($\omega_0 = \pi/2$)	297
A.7.6	Seven-Step PSA with a First-Order Zero at $\omega = 0$ and a Fifth-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	298
A.7.7	Seven-Step (6LS + 1) PSA with a Second-Order Zero at $-\omega_0$ ($\omega_0 = 2\pi/6$)	299
A.8	Eight-Step Linear PSAs	300

A.8.1	Eight-Step Least-Squares PSA ($\omega_0 = 2\pi/8$)	300
A.8.2	Eight-Step Frequency-Shifted LS-PSA ($\omega_0 = 2 \times 2\pi/8$)	301
A.8.3	Eight-Step PSA with First-Order Zeros at $\{0, -\omega_0, \pm 2\omega_0, \pi/10, -3\pi/10, -7\pi/10, 9\pi/10\}$	302
A.8.4	Eight-Step PSA with Second-Order Zeros at $\{0, \pm 2\omega_0\}$ and a Third-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	303
A.8.5	Eight-Step PSA with First-Order Zeros at $\{0, -\pi/6, -5\pi/6, \pm 2\omega_0\}$ and a Fourth-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	304
A.8.6	Eight-Step PSA with First-Order Zeros at $\{0, \pm 2\omega_0\}$ and a Fifth-Order Zero at $-\omega_0$ ($\omega_0 = \pi/2$)	305
A.9	Nine-Step Linear PSAs	306
A.9.1	Nine-Step Least-Squares PSA ($\omega_0 = 2\pi/9$)	306
A.9.2	Nine-Step PSA with First-Order Zeros at $\{0, \pm 2\omega_0\}$ and Second-Order Zeros at $\{-\omega_0, -\pi/4, -3\pi/4\}$ ($\omega_0 = \pi/2$)	307
A.9.3	Nine-Step (8LS + 1) PSA ($\omega_0 = 2\pi/8$)	308
A.10	Ten-Step Linear PSAs	309
A.10.1	Ten-Step Least-Squares PSA ($\omega_0 = 2\pi/10$)	309
A.10.2	Ten-Step PSA with a First-Order Zero at $\omega = 0$ and Second-Order Zeros at $\{-\omega_0, \pm 2\omega_0, \pm 3\omega_0\}$ ($\omega_0 = \pi/3$)	310
A.11	Eleven-Step Linear PSAs	311
A.11.1	Eleven-Step Least-Squares PSA ($\omega_0 = 2\pi/11$)	311
A.11.2	Eleven-Step PSA with Second-Order Zeros at $\{0, -\omega_0, \pm 2\omega_0, \pm 3\omega_0\}$ ($\omega_0 = \pi/3$)	312
A.11.3	Eleven-Step Frequency-Shifted LS-PSA ($\omega_0 = 3 \times 2\pi/11$)	313
A.12	Twelve-step linear PSAs	314
A.12.1	Twelve-step frequency-shifted LS-PSA ($\omega_0 = 5 \times 2\pi/12$)	314

References 315

Index 325